

Cemimax PP8 Low-Slump Cementitious Repair Mortar

BPIR Declaration

Version: V1

Designated building product: Class 1

Declaration

Cemimax New Zealand Limited has provided this declaration to satisfy the provisions of Schedule 1(d) of the Building (Building Product Information Requirements) Regulations 2022.

Product/system

Name	Cemimax PP8 Low-Slump Cementitious Repair Mortar
Line	Low slump and rapid strength cementitious repair mortar for patching, repairing and filling of holes.
Identifier	

Description

Cemimax PP8 is a low slump and rapid strength cementitious repair mortar for patching, repairing and filling of holes. Suitable for subfloor preparation to levelling and installation work. It provides a high strength and smooth surface for covering.

Scope of use

- Resistant to impact and vibration.
- Fast drying, ready to cover in 60 mins.
- Up to 100mm.
- Fine grain, smooth surface.
- Water adds: 4.6-5.4 L for 20kg bag.
- Concrete.
- Compressive strength:35MPA /28d.

Conditions of use

Surface/Substate Preparation:

The substrate to be grouted must be clean, sound, and free from dust, oil, grease, curing compounds or any foreign matter that will affect the grout adhesion bond Bolt holes and anchor points must be clean and free of water.

Application:

- Put 4.6-5.4 liters of cold clean water into a clean container. Sprinkle in the sack contents (20kg.) whilst stirring briskly with a drill fitted with box/ square style paddle mixer and mix to a thick, creamy, lump-free, peanut butter like consistency. Do not mix too thinly.
- Trowel the mixture on the area to be applied, spread the material uniformly. Smooth to a flat, smooth finish with proper trowel and if needed while installing do not apply water directly to PP8 but to the trowel and smooth. If product becomes too dry to trowel out of the bucket it may be re-whipped to bring back to life. *Do not add more water when re-whipping.*

- Drying time is approx. 30 minutes; high depth installation will delay the dry time. If needed, abrade using 40-60 grit sandpaper. It improves both the surface quality and absorbency. Poor airflow, thicker applications, and lower temperatures will significantly affect drying times.

Contributions to compliance

B2.3.1(b) (ii) Cemimax PP8 has durability of at least 15 years. F2.3.1 Cemimax PP8 is safe when handled correctly as per Application Instructions on TDS.

Contact details

Manufacture location	Overseas
Legal and trading name of manufacturer	Cemimax Australia Pty Ltd
Legal and trading name of importer	Cemimax New Zealand Limited
Importer address for service	23A Canaveral Drive, Rosedale Auckland 0632
Importer website	
Importer NZBN	9429051766979
Importer email	info@cemimax.co.nz
Importer phone number	02102313450

Responsible person

As the responsible person as set out in Regulation 3, I confirm that the information supplied in this declaration is based on information supplied to the company as well

as the company's own processes and is therefore to the best of my knowledge, correct.

I can also confirm that Cemimax PP8 Low-Slump Cementitious Repair Mortar is not subject to a warning or ban under [s26 of the Building Act](#).

Signed for and on behalf of **Cemimax New Zealand Limited**:



Jeff Xu

Director

June 2026



CEMIMAX NEW ZEALAND LIMITED

23A Canaveral Drive, Rosedale Auckland 0632 New Zealand

02102313450 | info@cemimax.co.nz